



Service Bulletin

SR-047

DATE: July 2, 2010
 TO: All Service and Parts Managers
 SUBJECT: Incorrect Aluminum Service Replacement Coils

We have received reports of incorrect aluminum service coils substitutions for the #1262404 and #1262405 copper service coils for some AR*F and A*PF air handlers, these substitutions have been deleted from our system. Air handlers listed in Table 1 require a 4 row/4 circuit coil and will continue to use the **#1262405 or #1262405C** coated coil.

Air handler Model
AR*F496116AA
AR*F374316BA
AEPF426016*A
A60-00-2RB
WAHMS4961P4AAA
WAHME4260P4ACA
ADPF486016BA
ASPF426016BA
WAHMS3743P4ABA

Table 1

Air handler models listed below in Table 2 will use the new aluminum service coils listed and are available from the Service Parts Department at HLC.

Air Handler Model	New Alum Service Coil
AR*F364216*A	0270A00412S
ADPF304216*A	
WAHMS3642P4A*A	
A48-00-2R*A	
AR*F486016*A	0270A00413S
AEPF313716*A	
ASPF313716*A	
WAHMS4860P4A*A	
ADPF182416*A	0270A00423S
AR*F182416*A	
WAHMS1824P4A*A	

Table 2

The Service Bulletin will be updated as new aluminum service coils are released for service and available from the Service Parts Department at HLC.

Technical Services Department • 1810 Wilson Parkway • Fayetteville, TN 37334
 Main: 888.593.9988 • Service Fax: 713.316.5546