



Unitary Products Group  
5005 York Drive  
Norman, OK 73069  
1/877-874-7378

## SERVICE INFORMATION

**DATE:** June 29, 2006

**YS-055-06**

**TO:** All York Branches and Distributors  
All York Service Managers  
All Field Service Supervisors

**SUBJECT:** G8C, GF8 & P6UH, Multi Positional, 31 1/2" Tall, 80% Furnace  
Air Leakage Around Vestibule Panel At Burners  
Kit Numbers #S1-37323842001 and #S1-37323842002

These kits are the result of product reports submitted on the subject:

Kits were developed to eliminate the air leakage around the vestibule panel at the burner box and prevent roll out switch nuisance tripping.



Please follow the step-by-step instructions supplied with the kit exactly when installing the kit.

There are two kits available:

Kit #S1-37323842001 is for the 50,000 to 100,000 input models.

Kit #S1-37323842002 is for the 125,000 and 150,000 input models.

Both kits contain two brackets for left and right sides of the vestibule panel burner box and a Limit Gasket for the backside of the limit control on all models.

Kit #S1-37323842001 for the 50,000 to 100,000 input models also contains:

Three sets of brackets for the top and bottom of the vestibule panel burner box of the 50,000, 75,000 and 100,000 input models.

Kit #S1-37323842002 for the 125,000 and 150,000 input models also contains:

Two sets of brackets for the top and bottom of the vestibule panel burner box of the 125,000 and 150,000 input models.

York will provide a 2 hr labor allowance per unit to install these kits as needed.

This is a fix on fail only.

File standard warranty claims and reference this service letter.

We apologize for any inconvenience this may have caused.

*Ron Butcher*

*Robert Cabrera*

Ron Butcher  
Field Service Supervisor

Robert Cabrera  
Senior Project Engineer